3- Minute Executive Summary

Association: Big Sky HOA Assoc. #: 13144-2

Location: Simi Valley, CA

of Units: 771

Report Period: June 1, 2016 through May 31, 2017

Results as-of 6/1/2016:

| Projected Starting Reserve Balance: | \$2,400,000 |
|---|---------------------------------------|
| Fully Funded Reserve Balance: | \$1,202,103 |
| Average Reserve Surplus Per Unit: | \$1,554 |
| Percent Funded: | |
| Recommended 2016/2017 monthly Reserve Contribution: | \$10.000 |
| Recommended 2016/2017 Special Assessment for Reserves:. | · · · · · · · · · · · · · · · · · · · |
| - | |

Most Recent Reserve Contribution Rate:\$10,000

Economic Assumptions:

| Net Annual "After Tax" Interest Earnings | s Accruing to Reserves1.00% |
|--|-----------------------------|
| Annual Inflation Rate | 3.00% |

- This is an "Update With-Site-Visit" Reserve Study, based on a prior Report prepared by Association Reserves for your 2015/2016 Fiscal Year. The information in this Reserve Study is based on our site inspection on March 25, 2016.
- This Reserve Study was prepared by, or under the supervision of, a credentialed Reserve Specialist (RS).
- Because your Reserve Fund is above 130% at 199.7% Funded, this represents a surplus Reserve Fund position. While Reserve Fund strength is desired, for fairness, stable cash flow and efficiency, it's best not to remain in a surplus position too long.
- Based on this starting point, your anticipated future expenses, and your historical Reserve contribution rate, our recommendation is to maintain your Reserve contributions.
- Your multi-year Funding Plan is designed to return you to the 100% level, or "Fully Funded" rapidly, without large cash flow volatility.

| Table 1 | : Executive Summary | | | | 13144-2 |
|--------------|--|----------|------------|-----------------------|-----------------------|
| | | | _ | _ | _ |
| | | Useful | Rem. | Current | Future |
| ш | Commonant | Life | Useful | Average | Average |
| # | Component | (yrs) | Life (yrs) | Cost | Cost |
| | General Common Area | | | | |
| 201 | Asphalt - Remove/Replace (Parking) | 28 | 16 | \$48,450 | \$77,748 |
| 202 | Asphalt - Seal/Repair | 5 | 3 | \$4,500 | \$4,917 |
| 206 | Special/Stamped Concrete - Replace | 20 | 9 | \$156,500 | \$204,197 |
| 306 | Exhaust Fan - Replace | 10 | 8 | \$1,600 | \$2,027 |
| 321 | Landscape Lights - Replace | 15 | 13 | \$11,000 | \$16,154 |
| 403 | Mailboxes & Posts - Replace | 20 | 18 | \$137,500 | \$234,085 |
| 406 | Dog Stations - Replace | 15 | 9 | \$5,100 | \$6,654 |
| 507 | Split Rail Concrete Fence - Repair | 1 | 1 | \$40,000 | \$41,200 |
| 507 | Split Rail Concrete Fence - Repair Project | N/A | 0 | \$300,000 | \$0 |
| 701 | Front Doors - Replace | 20 | 9 | \$3,500 | \$4,567 |
| 708 | Trash Gates - Replace | 20 | 9 | \$2,500 | \$3,262 |
| 1001 | Backflow Devices - Partial Replace | 3 | 1 | \$14,900 | \$15,347 |
| 1002 | Irrigation Pumps - Replace (A) | 10 | 0 | \$126,000 | \$169,333 |
| 1002 | Irrigation Pumps - Replace (B) | 10 | 8 | \$36,000 | \$45,604 |
| 1003 | IQ Irrigation Controllers - Replace | 12 | 10 | \$212,500 | \$285,582 |
| 1004 | Backflow Enclosures - Replace | 30 | 19 | \$49,500 \$77,500 | \$86,799 |
| 1004 | Pump Enclosures - Replace | 20 | 9 | \$77,500 \$70,000 | \$101,120 |
| 1004 | Time Clock Enclosures - Replace | 25 | 14 | \$70,000 \$40,500 | \$105,881 |
| 1004 | Time Clock Enclosures - Replace (SS) | 30 | 28 | \$10,500 | \$24,023 |
| 1005 | Irrigation System - Refurbish | 1 | 0 | \$35,000 \$463,500 | \$36,050 \$473,457 |
| 1107 1114 | Galvanized Fence - Repaint (50%) | 5 | 2 | \$163,500 \$50,000 | \$173,457 |
| 1114 | Mailboxes - Repaint Mailboxes Stands - Repaint | 10 10 | 8 | \$50,000 \$50,000 | \$63,339 \$63,330 |
| 1114 | Waterscape Building - Repaint | 10 | 8 8 | \$50,000 \$7,500 | \$63,339 \$9,501 |
| 1207 | Waterscape Filter - Replace | 8 | 6 | \$1,750 | \$2,090 |
| 1210 | Waterscape Pump - Replace (large) | 10 | 3 | \$1,750 \$18,750 | \$2,090 \$20,489 |
| 1210 | Waterscape Pump - Replace (small) | 8 | 6 | \$2,000 | \$2,388 |
| 1302 | Cap Sheet Roof - Replace | 20 | 9 | \$2,550 | \$3,32 7 |
| 1304 | Tile Roof - Replace Underlayment | 30 | 19 | \$22,300 | \$39,103 |
| 1402 | Monument Signs - Refurbish | 10 | 8 | \$12,500 | \$15,835 |
| | menament eighe Relandien | | • | 4.2,000 | \$10,000 |
| | Glenmeadow | | | | |
| 201 | Asphalt - Remove/Replace | 28 | 17 | \$420,000 | \$694,196 |
| 202 | Asphalt - Seal/Repair | 5 | 3 | \$20,300 | \$22,182 |
| 206 | Stamped Concrete - Replace | 20 | 0 | \$94,500 | \$170,678 |
| 503 | Metal Fence/Rail - Replace | 24 | 14 | \$7,400 | \$11,193 |
| 503 | Vehicle Gates - Replace | 24 | 14 | \$42,000 | \$63,529 |
| 504 | Vehicle Gates - Repair | 8 | 1 | \$2,000 | \$2,060 |
| 704 | Intercoms - Replace | 15 | 0 | \$8,000 | \$12,464 |
| 705 | Gate Operator - Replace | 12 | 2 | \$26,000 | \$27,583 |
| 440= | | _ | _ | A0 F00 | A |

³⁹ Total Funded Components

1107

Metal Fence/Rail - Repaint

5

\$3,825

\$3,500

Note 1: a Useful Life of "N/A" means a one-time expense, not expected to repeat.

Note 2: highlighted line items are expected to require attention in the initial year